

~~SECRET~~  
P/N 389813-PH, J-75 FUEL CONTROL STATUS

AS OF: 24 January 1964

<u>SERIAL NUMBER</u>	<u>LOCATION</u>	<u>INST. ENGINE</u>	<u>INST. ARTICLE</u>	<u>SERV.</u>	<u>REP.</u>	<u>ETIC</u>	<u>REMARKS</u>
14794	Hamilton Standard				X	April	Overhaul 25X1A
20928					X		In Transit to Depot
21236	Hamilton Standard				X	Unk.	Overhaul
25X1A							
21237							Being Held 25X1A Pending Flight Check 358
21238					X		In Transit to Depot
25X1A							
21240							Being Held Pending Flight Check 358
21248					X		In Transit to Depot
22726					X		Detachment In Transit to Depot
22727	Hamilton Standard				X	Feb.	Overhaul 25X1A
22728					X		Removed 358 In Transit to Depot
23014					X		Detachment In Transit to Depot
23349	PAC				X		Overhaul, Emergency System Revealed Low Flows At Several Points. (Rec 25X1A From )

~~SECRET~~

Approved For Release 2002/06/14 : CIA-RDP81B00961R000100160077-5

<u>SERIAL NUMBER</u>	<u>LOCATION</u>	<u>INST. ENGINE</u>	<u>INST. ARTICLE</u>	<u>SERV.</u>	<u>REP.</u>	<u>ETIC</u>	<u>REMARKS</u>
23350	PAC				X		25X1A Overhaul For Calibration (Rec. from [redacted])
24777	LAC	612432	348				Conversion
24778	25X1A [redacted]	610427	356	X			To Be Flight Checked 23 Jan. or When Weather Permits
24779	P&W East				X		25X1A Per Request [redacted] For Test and Tear Down
35008	25X1A [redacted]	610426	359				Presently Under Flight Test 24 Jan 64
35009	LAC	612412	362				A/C Conversion
35114	PAC				X		Overhaul
35115	PAC				X		Overhaul - Bad Seals. Special Seat Kit P/N 18404 Banner to PAC to Complete Assy and Overhaul

~~SECRET~~